



IECEX Quality Assessment Report

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification Scheme for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Reference No.	GB/BAS/QAR06.0017/08	Status	Current
QAR Free Ref. No.	1112	Date of Issue	2018-06-21
Detail of change	Re-Assessment audit completed	Valid until	2021-03-27
Site(s) audited	The Wolf Safety Lamp Co. Limited, Saxon Road Works, Sheffield, S8 0YA	Audit date	2018-03-27
Issuing ExCB	BAS - SGS Baseefa Limited		
Manufacturer	The Wolf Safety Lamp Co. Limited, Saxon Road Works, Sheffield, S8 0YA		
Country of Manufacturer	United Kingdom		
Product information	Torches, Luminaires, lamps		
Protection concept	"e", "ib", "ia", "m", "t" "op is" and "d"		

Related QARs

GB/BAS/QAR06.0017/00	GB/BAS/QAR06.0017/01	GB/BAS/QAR06.0017/02	GB/BAS/QAR06.0017/03
GB/BAS/QAR06.0017/04	GB/BAS/QAR06.0017/05	GB/BAS/QAR06.0017/06	GB/BAS/QAR06.0017/07
GB/BAS/QAR06.0017/08			

Related Certificates (manual insertion)
IECEX TSA 05.0017X

Related Certificates (automatic linking)

N/A

Related Certificates for previous versions

IECEX BAS 06.0001 issue: 1	IECEX BAS 06.0001 issue: 2	IECEX BAS 06.0001 issue: 3	IECEX BAS 06.0001 issue: 4
IECEX BAS 06.0001 issue: 5	IECEX BAS 06.0001X issue: 6	IECEX BAS 06.0001X issue: 7	IECEX BAS 06.0023 issue: 0
IECEX BAS 06.0023 issue: 1	IECEX BAS 06.0023 issue: 2	IECEX BAS 06.0023 issue: 3	IECEX BAS 06.0023 issue: 4
IECEX BAS 06.0023X issue: 5	IECEX BAS 06.0023X issue: 6	IECEX BAS 06.0089 issue: 0	IECEX BAS 06.0089 issue: 1
IECEX BAS 06.0089 issue: 2	IECEX BAS 06.0089 issue: 3	IECEX BAS 06.0089X issue: 4	IECEX BAS 06.0089X issue: 5
IECEX BAS 09.0153 issue: 0	IECEX BAS 09.0153 issue: 1	IECEX BAS 09.0153 issue: 2	IECEX BAS 09.0153 issue: 3
IECEX BAS 09.0153X issue: 4	IECEX BAS 09.0153X issue: 5	IECEX BAS 10.0023 issue: 0	IECEX BAS 10.0023 issue: 1
IECEX BAS 10.0023 issue: 2	IECEX BAS 10.0023X issue: 3	IECEX BAS 10.0023X issue: 4	IECEX BAS 11.0116 issue: 0
IECEX BAS 11.0116 issue: 1	IECEX BAS 11.0116X issue: 2	IECEX BAS 11.0116X issue: 3	IECEX BAS 14.0095 issue: 0
IECEX BAS 14.0095 issue: 1	IECEX BAS 15.0033X issue: 0	IECEX BAS 15.0033X issue: 1	IECEX BAS 16.0073X issue: 0
IECEX BAS 16.0073X issue: 1	IECEX BAS 16.0076X issue: 0	IECEX SIR 10.0016X issue: 0	IECEX SIR 10.0016X issue: 1
IECEX SIR 10.0016X issue: 2	IECEX SIR 10.0016X issue: 3	IECEX SIR 10.0016X issue: 4	IECEX SIR 10.0016X issue: 5
IECEX SIR 10.0121 issue: 0	IECEX SIR 10.0121 issue: 1	IECEX SIR 10.0121X issue: 2	IECEX SIR 10.0121X issue: 3
IECEX SIR 12.0070X issue: 0	IECEX SIR 12.0070X issue: 1	IECEX SIR 12.0070X issue: 2	IECEX SIR 12.0070X issue: 3
IECEX SIR 12.0070X issue: 4	IECEX SIR 12.0070X issue: 5	IECEX SIR 12.0070X issue: 6	IECEX SIR 15.0115X issue: 0
IECEX SIR 15.0115X issue: 1	IECEX SIR 17.0013X issue: 0		

Comments

N/A