



IECEX Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.: **GB/BAS/QAR06.0017/09** Page 1 of 2

QAR Free Ref. No.: **1112** Status: **Issued**

Details of change: **Surveillance audit completed** Date of issue: **2020-01-07**

Site(s) audited: **The Wolf Safety Lamp Co. Limited** Valid until: **2021-03-27**
 Saxon Road Works
 Sheffield
 S8 0YA
United Kingdom Audit date: **2019-11-07**

Issuing ExCB: **BAS - SGS Baseefa Limited**

Manufacturer: **The Wolf Safety Lamp Co. Limited**
 Saxon Road Works
 Sheffield
 S8 0YA

Location of Manufacturer: **United Kingdom**

Product information: **Torches, Luminaires, lamps**

Protection concept: **Ex 'd' 'e' 'i' 'm' 't' 'op is'**

Related QARs:

GB/BAS/QAR06.0017/00	GB/BAS/QAR06.0017/01	GB/BAS/QAR06.0017/02
GB/BAS/QAR06.0017/03	GB/BAS/QAR06.0017/04	GB/BAS/QAR06.0017/05
GB/BAS/QAR06.0017/06	GB/BAS/QAR06.0017/07	GB/BAS/QAR06.0017/08

Related Certificates (manual insertion): **IECEX TSA 05.0017X**

Related Certificates (automatic linking): [IECEX CML 18.0197X issue: 0](#)
[IECEX CML 18.0197X issue: 1](#)
[IECEX CML 18.0199X issue: 1](#)
[IECEX BAS 06.0001X issue: 8](#)

Related Certificates for previous versions:

IECEX BAS 06.0001 issue: 1	IECEX BAS 06.0001 issue: 2	IECEX BAS 06.0001 issue: 3
IECEX BAS 06.0001 issue: 4	IECEX BAS 06.0001 issue: 5	IECEX BAS 06.0001X issue: 6
IECEX BAS 06.0001X issue: 7	IECEX BAS 06.0023 issue: 0	IECEX BAS 06.0023 issue: 1
IECEX BAS 06.0023 issue: 2	IECEX BAS 06.0023 issue: 3	IECEX BAS 06.0023 issue: 4
IECEX BAS 06.0023X issue: 5	IECEX BAS 06.0023X issue: 6	IECEX BAS 06.0023X issue: 7
IECEX BAS 06.0089 issue: 0	IECEX BAS 06.0089 issue: 1	IECEX BAS 06.0089 issue: 2
IECEX BAS 06.0089 issue: 3	IECEX BAS 06.0089X issue: 4	IECEX BAS 06.0089X issue: 5
IECEX BAS 09.0153 issue: 0	IECEX BAS 09.0153 issue: 1	IECEX BAS 09.0153 issue: 2
IECEX BAS 09.0153 issue: 3	IECEX BAS 09.0153X issue: 4	IECEX BAS 09.0153X issue: 5
IECEX BAS 09.0153X issue: 6	IECEX BAS 09.0153X issue: 7	IECEX BAS 10.0023 issue: 0
IECEX BAS 10.0023 issue: 1	IECEX BAS 10.0023 issue: 2	IECEX BAS 10.0023X issue: 3
IECEX BAS 10.0023X issue: 4	IECEX BAS 11.0116 issue: 0	IECEX BAS 11.0116 issue: 1
IECEX BAS 11.0116X issue: 2	IECEX BAS 11.0116X issue: 3	IECEX BAS 14.0095 issue: 0
IECEX BAS 14.0095 issue: 1	IECEX BAS 15.0033X issue: 0	IECEX BAS 15.0033X issue: 1



IECEX Quality Assessment Report Summary

Related Certificates for
previous versions (continued):

IECEX BAS 15.0033X issue: 2
IECEX BAS 16.0076X issue: 0
IECEX CML 18.0199X issue: 0
IECEX SIR 10.0016X issue: 1
IECEX SIR 10.0016X issue: 4
IECEX SIR 10.0121 issue: 1
IECEX SIR 12.0070X issue: 0
IECEX SIR 12.0070X issue: 3
IECEX SIR 12.0070X issue: 6
IECEX SIR 15.0115X issue: 0
IECEX SIR 17.0013X issue: 1

IECEX BAS 16.0073X issue: 0
IECEX CML 18.0198X issue: 0
IECEX CML 19.0005X issue: 0
IECEX SIR 10.0016X issue: 2
IECEX SIR 10.0016X issue: 5
IECEX SIR 10.0121X issue: 2
IECEX SIR 12.0070X issue: 1
IECEX SIR 12.0070X issue: 4
IECEX SIR 12.0070X issue: 7
IECEX SIR 15.0115X issue: 1
IECEX SIR 18.0028X issue: 0

IECEX BAS 16.0073X issue: 1
IECEX CML 18.0198X issue: 1
IECEX SIR 10.0016X issue: 0
IECEX SIR 10.0016X issue: 3
IECEX SIR 10.0121 issue: 0
IECEX SIR 10.0121X issue: 3
IECEX SIR 12.0070X issue: 2
IECEX SIR 12.0070X issue: 5
IECEX SIR 12.0070X issue: 8
IECEX SIR 17.0013X issue: 0

Comments: